





www.elsevier.com/locate/jpowsour

Electron microscopic characterization of electrochemically cycled LiCoO₂ and Li(Al,Co)O₂ battery cathodes

Haifeng Wang, Young-Il Jang, Biying Huang, Donald R. Sadoway, Yet-Ming Chiang *

Department of Materials Science and Engineering, Massachusetts Institute of Technology, Cambridge, MA 02139, USA

Abstract

Electrochemical cycling of lithium battery cathodes introduces large absolute changes in lithium concentration that can result in microstructural damage and cation disorder. This damage can influence the long-term performance of battery systems, but has not to date been investigated in detail. We have conducted direct observations using transmission electron microscopy (TEM) of electrochemically cycled $\text{Li}_x \text{CoO}_2$ and $\text{Li}_x \text{Al}_y \text{Co}_{1-y} \text{O}_2$ cathodes. A rich variety of electrochemical cycling-induced damage is found. Intercalation oxide particles show widely varying degrees of damage suggesting differing depths of cycling on a local scale. Many particles exhibit severe strain, high dislocation densities, and localized fracture. Moreover, in particles that are severely strained, electron diffraction reveals two types of cation disorder brought about by electrochemical cycling. One is the Li and Co substitution/vacancies on their respective octahedral layers. The second is an evolution towards spinel ordering that is not detectable by bulk analytical methods such as X-ray diffraction (XRD). Unlike previously described 'lithiated spinels,' the observed spinel ordering is characterized by tetrahedral 8a site occupancy even at compositions near $x \sim 1$. Thus it is shown that even in LiCoO_2 , widely considered to be the most stable of the intercalation oxides in the layered α -NaFeO₂ structure, electrochemical cycling results in a transformation towards spinel cation ordering. Similar results are seen in $\text{Li}_x \text{Al}_y \text{Co}_{1-y} \text{O}_2$. Cumulative damage of this kind may contribute to the degradation of LiCoO_2 cathodes after long-term cycling. © 1999 Elsevier Science S.A. All rights reserved.

Keywords: Electron microscopy; LiCoO2; Li(Al,Co)O2; Battery cathodes

1. Introduction


An ideal cathode material for the lithium rechargeable battery should have an outstanding electrochemical performance, stable capacity upon extended cycling, and low cost. Of the lithium transition metal oxides (LiMO₂, M =Sc, Ti, V, Cr, Mn, Fe, Co, Ni), LiCoO₂ is considered to be amongst the most stable in the layered α-NaFeO₂ structure. LiCoO₂ synthesized by firing at high temperatures has a highly ordered cation sublattice in which Li and Co ions occupy alternating {111} layers of octahedral sites in a nearly cubic close-packed oxygen sublattice [1-4]. The structure is rhombohedral (R3m space group) with lattice parameters a = 2.816 Å and c = 14.051 Å in the hexagonal setting [1,3]. The remarkable electrochemical stability of layered LiCoO₂ upon extended cycling has largely been attributed to its structural stability, wherein the layered cation ordering is well preserved during repeated insertion and removal of Li⁺. It has been found that while Li_xCoO₂ undergoes a sequence of transformations from monoclinic through hexagonal phase during delithiation as $x \to 0$ [5–7], the cations are believed to remain octahedrally coordinated throughout. The typical reversible limit of delithiation for Li_xCoO_2 in commercial batteries is x=0.5, which corresponds to a charge capacity of ~ 140 mA h/g. Instability at higher delithiation is believed due to the mechanical failure associated with a large dimension change, rather than any change in cation ordering. However, few if any direct observations have been made to date of changes in the cathode oxide during repeated cycling.

In order to characterize the cathode materials on a microscopic scale, we used transmission electron microscopy (TEM) to directly examine cycling-induced damage to cathode particles in typical composite cathodes. Changes in cation ordering resulting from repeated cycling were observed using single crystal selected area electron diffraction (SAD) of individual particles. Both LiCoO₂ and LiAl_{0.25}Co_{0.75}O₂ materials were studied, the latter being of interest due to the effect of Al doping on intercalation voltage [8] and cycling properties [9].

^{*} Corresponding author

2. Experimental

Powders of LiCoO₂ were synthesized by firing hydroxide precursors at 800°C for 2 h [11]. As-fired powders were characterized by X-ray diffraction (XRD) and SAD, as shown in Fig. 1. They showed that the starting materials had a well ordered α-NaFeO₂ structure. As detailed in Ref. [12], cathodes were prepared by mixing the as-calcined oxide powders with carbon black (Cabot), graphite (TIM-CAL America) and poly(vinylidene fluoride) (PVDF; Aldrich). The test cells used two stainless steel electrodes with a teflon holder. Lithium ribbon was used as the anode and a 1-M solution of LiPF₆ in ethylene carbonate (EC) and diethylene carbonate (DEC) (EC:DEC = 1:1 by volume) as the electrolyte. The cells were electrochemically cycled 50 times between 2.5 and 4.35 V for LiCoO₂ and 20 times between 2.0 and 4.5 V for LiAl_{0.25}Co_{0.75}O₂, at the charging and discharging current density of 0.4 mA/cm^2 (C/5 rate), and terminated in the discharged state at 2.5 V. As shown in Fig. 2, after some initial fade, the discharge capacity in the LiCoO₂ is well maintained at






Fig. 1. Experimental (a) XRD and (b) single crystal SAD pattern (zone axis = [0001]) for as-calcined LiCoO₂ powders.




Fig. 2. Specific capacity vs. cycle number for $LiCoO_2$ cathode (Li anode) cycled between 2.5 and 4.35 V at 0.4 mA/cm² (C/5 rate).


approximately 130 mA h/g up to 50 cycles. In the $LiAl_{0.25}Co_{0.75}O_2$, greater cycling fade was observed as discussed in Ref. [9].

TEM samples were extracted from the cycled cathode pellets. Pieces of cathodes were ultrasonically de-agglomerated and dispersed on amorphous carbon film supported by a copper grid. Bright field imaging and SAD were conducted on clearly separated particles. Low index zone axes were found by tilting the sample around two axes. Oxide particles were stable during the observation under electron beam.

Single crystal SAD patterns, as well as XRD spectra were also computed for a large number of possible derivatives of the ideal layered structure, using commercial software [13], as presented in detail elsewhere [10]. The simulated results from model structures were compared with experimental results to identify the changes in cation ordering.

3. Cycling-induced microstructural damage

Fig. 3 shows the LiCoO₂ particles before and after electrochemical cycling. As-calcined particles, 300 to 500 nm in size, display little variation in contrast across the individual particle except for that due to thickness variation. It is consistent with the SAD result (Fig. 1) showing a high level of crystalline perfection. After repeated cycling, some particles exhibit non-uniform diffraction contrast within each particle, due to lattice strain, dislocations and defects, while the rest are lightly strained or remain unchanged. In particular, as shown in Fig. 4, some particles are severely strained with extensive internal defects and microcracks. Severely damaged particles represent about 20% of the total examined, while 50% of the total show some sign of damage. It is believed that damage can result from at least two possible mechanisms. One is differential lattice expansion and contraction due to local variation in Li concentration. Another is constrained deformation due






Fig. 3. TEM bright field image of (a) as-fired $LiCoO_2$ powders; (b) $LiCoO_2$ powders after 50 cycles between 2.5 and 4.35 V. Note diffraction contrast from internal strain and extended defects in the latter.

to the presence of sintered polycrystalline aggregates, upon charging/discharging-induced lattice expansion and contraction. These effects all can combine to result in the creation of localized irreversible crystallographic defects.




Fig. 4. Severely damaged $LiCoO_2$ particle from cycled cathode showing microcracks (arrows) and strong diffraction contrast form internal strain and extended defects.




Fig. 5. Experimental SAD pattern of cycled $LiCoO_2$ particle with low strain, indexed according to the hexagonal setting, exhibits new $\{10\overline{1}0\}$ reflections indicating the Li/Co substitution/vacancy on octahedral site layers [10].

It is apparent that electrochemical cycling does not occur uniformly everywhere within the cathode. A wide variation in the depth of charge/discharge of active oxide particles is implied by the observations.

4. Cycling-induced cation disorder

Close investigation of single crystal SAD patterns of strained particles shows that two types of cation disorder occur in the cycled LiCoO_2 powders. One is cation mixing between Li and Co octahedral site layers. This is indicated by the appearance of $\{10\overline{1}0\}$ reflections, as shown in Fig. 5. These diffraction spots are very weak even when com-




Fig. 6. Experimental SAD pattern from severely strained $LiCoO_2$ particles exhibits a new family of reflections {220}, indexed only in cubic setting, indicating cation occupancy on 8a tetrahedral sites [10].




Fig. 7. TEM bright field images LiAl_{0.25}Co_{0.75}O₂ particles and corresponding SAD patterns from circled particles. (a) Before electrochemical cycling. (b) After cycling, illustrating internal strain and extended defects created by repeated Li insertion/removal.

plete disorder between Li and Co layers is assumed (e.g., each layer has 50% Li and 50% Co) [10]. Another significant type of cation disorder is found only for severely strained particles (example shown in Fig. 4). New strong {220} reflections (Fig. 6) are observed, which are characteristic of the cubic spinel structure with tetrahedral 8a occupancy of cations. This is the first observation of spinel disorder in LiCoO₂ due to electrochemical cycling, and suggests that the stable structure at intermediate Li concentration may be the spinel, as is also indicated by ab initio computations [14]. Continued development of spinel disorder may occur after longer cycling. Whether this mechanism alone, or disorder combined with microstructural damage, contributes to the long-term degradation of LiCoO₂ cathodes requires additional study.

In the LiAl_{0.25}Co_{0.75}O₂ cathode, similar electrochemical cycling-induced strain damage was readily observed by TEM (Fig. 7). However, in contrast to the LiCoO₂ sample, we found fewer instances where the {220} reflections characteristic of spinel disorder appeared. While more extensive studies are necessary, the results suggest that aluminum doping stabilizes LiCoO₂ against spinel disorder during electrochemical cycling. However, since the

 ${\rm LiAI_{0.25}Co_{0.75}O_2}$ cathode does show greater capacity fade [9], it appears that another mechanism of capacity loss apart from the spinel transformation may be active. It is notable that aluminum doping has been found to stabilize the layered rocksalt phases monoclinic ${\rm LiMnO_2}$ [15] and rhombohedral ${\rm LiNiO_2}$ [9] during synthesis. Aluminum substitution into the transition metal oxides of ${\rm LiMO_2}$ stoichiometry may generally serve a role of stabilizing layered rocksalt ordering.

5. Conclusions

Direct TEM observation of cycled cathode materials LiCoO₂ and LiAl_{0.25}Co_{0.75}O₂ shows that a wide variety of defects are created. Particles are extensively strained or microfractured, and often contain a high density of dislocations and extended defects. Single crystalline SAD patterns reveal two types of cation disorder resulting from the repeated insertion and removal of Li⁺. One is the cation substitution/vacancy of Li and Co on their respective octahedral site layers in the ordered α-NaFeO₂ structure. The second, mainly observed in severely strained and fractured particles, is a partial structural transformation from octahedral cation ordering to spinel ordering with tetrahedral 8a site occupancy. These cycling effects are not detectable by bulk characterization methods such as XRD. The observed cation disorder provides the first direct experimental evidence for the stability of a spinel phase in Li "CoO₂.

Acknowledgements

The authors are grateful for fruitful discussions with G. Ceder and A. van der Ven. This work was funded by the INEEL University Research Consortium, managed by Lockheed Martin Idaho Technology for DOE, Idaho Operations Offices under contract number DE-AC07-94ID13223. Shared Experimental Facilities in the Center for Materials Science and Engineering at MIT, supported by NSF Grant No. 9400334-DMR, are also acknowledged.

References

- W.D. Johnston, R.R. Heikes, D. Sestrich, J. Phys. Chem. Solids 7 (1958) 1.
- [2] K. Mizushima, P.C. Jones, P.J. Wiseman, J.B. Goodenough, Mater. Res. Bull. 15 (1980) 783.
- [3] H.J. Orman, P.J. Wiseman, Acta Cryst. C 40 (1984) 12-14.
- [4] T.A. Hewston, B.L. Chamberland, J. Phys. Chem. Solids 48 (1987) 97
- [5] J.N. Reimers, J.R. Dahn, J. Electrochem. Soc. 139 (1992) 8.
- [6] G.G. Amatucci, J.M. Tarascon, L.C. Klein, J. Electrochem. Soc. 143 (1996) 3
- [7] T. Ohzuku, A. Ueda, J. Electrochem. Soc. 141 (1994) 2972.

- [8] G. Ceder, Y.-M. Chiang, D.R. Sadoway, M.K. Aydinol, Y.-I. Jang, B. Huang, Nature 392 (1998) 694.
- [9] Y.-I. Jang, B. Huang, H. Wang, G.R. Maskaly, Y.-M. Chiang, D.R. Sadoway, these proceedings.
- [10] H. Wang, Y.-I. Jang, B. Huang, D.R. Sadoway, Y.-M. Chiang, in press.
- [11] Y.-M. Chiang, Y.-I. Jang, H. Wang, B. Huang, D.R. Sadoway, P.X. Ye, J. Electrochem. Soc. 145 (1998) 887.
- [12] B. Huang, Y.-I. Jang, Y.-M. Chiang, D.R. Sadoway, J. Appl. Electrochem., in press.
- [13] Cerius², version 3.5, Molecular Simulation, Inc., San Diego, CA, USA
- [14] A. van der Ven, G. Ceder, unpublished work.
- [15] Y.-I. Jang, B. Huang, Y.-M. Chiang, D.R. Sadoway, Electrochem. Solid State Lett. 1 (1) (1998) 13.